

Chabot-Las Positas Community College District

CHANGE ORDER

		OHANGE	UNDER			
OWNER ARCHITECT CONTRACTOR	Chabot-Las Positas C Arch Pac Aquatics Armour Fence	Community College	District		ntract No. roject No.	19/20-17 552640
PROJECT:	Chabot College Poo	l Renovation	CHANGE ORDER NI INITIATIO	UMBER:	001 October 2	20, 2020
TO (Contractor):	Armour Fence 165 Eucalyptus Aven Hillsborough, CA 94	010	CONTRAC CONTRAC	CT FOR: T DATE:	Bid No. 19 July 27, 20	9/20-17 020
Not valid until signe including any adjus	ed by both the Owner a stment in the Contract S	ind Architect. Signa Sum or Contract Tii	ature of the Contractor in the.	ndicates f	nis agreeme	nt nerewith,
Net change b The Contract The Contract	ONTRACT SUM y previously authorized Sum prior to this Chan Sum will be (increased tract Sum including this	ge Order was I) by this Change C	Order		\$ 249,000. \$ 00. \$ 249,000. \$ 45,911. \$ 294,911.	00 00 62
CONTRACT Contract Com The Contract The Date of Contract		dd (+) ate of this Change (Order therefore is:	57	Ocalendar D October 4, 2 Calendar D rember 30, 2	2020 Days
AUTHORIZED:						
Architect: Arch Pac Aquatics 1341 Distribution Vista, CA 92081	Way Suite 11	Contractor: Armour Fence 165 Eucalyptus Av Hillsborough, CA	C enue 76	wner: LPCCD 600 Dubli ublin, CA	n Boulevard 94568	, 3 rd Floor
By	ull_	By M By	h	у		

Date 210012020

Michael Garr

Project Planner/Manager: Facilities/Bond Program

Date

Owen Letcher

Vice Chancellor: Facilities

Bond Program and Operations

Date _____

CHANGE ORDER # 001

Date 21005 2020

Project Manager:

CCM/STV JV

Peter Espinosa

PROJECT NAME: CHABOT COLLEGE POOL RENOVATION, PHASE 2 - NEW FENCE

Change Order #: 001

Project Name: Chabot College Pool Renovation

Page 2 of 2

Change Order #: 001

Project #: 552640

Pursuant to the General Conditions, this Change Order Form shall be used for all Change Orders associated with the Work. No additions or deletions to this form shall be allowed, except with permission of the District.

You are hereby directed to provide the extra work necessary to comply with this Change Order.

1. DESCRIPTION OF CHANGE: PCO 001: Various Changes

a. Requested by: District

b. Reason: Existing conditions not covered in original scope of work

Add: \$45,911.62

	Sales Tax (9.75%) \$0.00 Total \$45,911.62		
	Subtotal	\$45,911.62	
1	278.11	278.11	
1	460,00	460.00	
1	940.00	940.00	
1	405.00	405.00	
1	905.00	905.00	
1	667.75	667.75	
1	7,720.00	7,720.00	
j	1,981.04	1,981.04	
1	2,580.40	2,580.40	
1	26,785.85	26,785.85	
	0.00	0.00	
1	2,710.50 477.97	2,710.50 477.97	
		1 2,580.40 1 1,981.04 1 7,720.00 1 667.75 1 905.00 1 405.00 1 940.00 1 278.11 Subtotal Sales Tax (9.75%)	

Total Cost of this Change Order:

\$ 45,911.62

CHANGE ORDER #001

ARHOUR FENCE

165 Eucalyptus Avenue Hillsborough, CA 94010

(714) 292-7572

Name / Address

Chabot-Las Positas CC District Peter Espinosa 505 14th Street, Sute 1060 Oakland, CA 94612

Estimate

Date	Estimate #
10/21/2020	2069

Description	Qty	Rate	Total	
Change Order Estimate				
Replacement of stair rails on wooden steps	1	2,710.50	2,710.50	
Temp Fence Addition around interior to allow swim/dive classes	1	477.97	477.97	
Ameristar height change for 1/2 of materials from 5' to 42"	1	0.00	0.00	
Additional 192LF of Ameristar fence for three ramps, including removal of existing guardrail, grinding embeds and filling with new topcoat, installing new fence with Titen HD screws	1	26,785.85	26,785.85	
Chain Link Fence Top rail size change from 2" to 2-1/2" square steel	1	2,580.40	2,580.40	
Adding casters on double swing gates	1	1,981.04	1,981.04	
Grinding, priming, and painting ramp handrails. Detaching and reattaching/welding handrails from existing guardrails to new Ameristar guardrails	1	7,720.00	7,720.00	
Moving wooden stairs (cutting, grinding bolt, patching pool deck, drilling new bolt hole, SS steel bolt). Credit of \$1,680.25 to reduce number of stair rails to one. Addition of two bolt holes and bolts for vertical wall.	1	667.75	667.75	
Black spray paint to cover all grout (installed by one union worker for 8 hours)	1	905.00	905.00	
Three welded vertical flange plates for post support	1	405.00	405.00	
ADA Ramp fencing adjustment (cut eight bolts, drill eight bolts, new fence ine alignment, reinstallation of two posts)	1	940.00	940.00	
16 additional bolts for Exodus gate posts (2/post). Drilling through steel plate and 4" of concrete. Three hours of labor.	1	460.00	460.00	
6-1/2" fasteners for exterior chain link posts (difference between 4" cost and 6-1/2" cost). No additional labor.	1	278.11	278.11	
		Subtotal	\$45,911.62	
		Sales Tax (9.75%) \$0.00 Total \$45,911.62		